


TR PROFILE

APPLICATIONS



Checking of surface roughness near a shoulder



Measurement in small bores




Measuring surface roughness of a polished part



Checking at recessed measuring points



Checking of thread profile roughness of a thread plug gage



Checking in a recess using an appropriate probe



Radial roughness measurement